

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS	
JS				ATT DENNIS SANITA	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
2/07/89	12/08/89	PD 8-77	A6472625	700 8MMAC BDL	R 89-30231
ACCESSORIES W/STUDS L/SIGHTS					

FROM:	SHIP TO:
LINE SAFETY SYSTEMS ATT DAVID MORSE 418 CUBBAGE AVE OWENTON KY 40359	LINE SAFETY SYSTEMS ATT DAVID MORSE 418 CUBBAGE AVE OWENTON KY 40359

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

RTS

12/19/89
Tupper adjusted 5pp, and tupper said
adjustment screw had been broken out,
tupper said measured 2 1/2 pounds
called Mr. Morse, he stated that the rifle
was given to him in lieu of payment for some
work he did
it agreed to replace tupper again at no charge
in getting it another good user
Thank you very much for JRS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 6/88

PPS 03021