

# RECEIVING AND ESTIMATING REPORT ✓

COMMENTS

ATTN: FRAN COLE

R90-31195

|                           |                              |                       |                           |                                   |                   |  |  |
|---------------------------|------------------------------|-----------------------|---------------------------|-----------------------------------|-------------------|--|--|
| INITIAL<br>FPS            | CUSTOMER ORDER NO.<br>011309 |                       |                           |                                   |                   |  |  |
| DATE RECEIVED<br>11/28/90 | DATE OPENED<br>12/03/90      | DATE CODE<br>EJ 10-89 | SERIAL NUMBER<br>C6448077 | MODEL AND GRADE<br>700 7MM LH BDL | ORDER<br>R 90-311 |  |  |
| ACCESSORIES<br>W/STUDS    |                              | SCOPE BASE            |                           | L/SIGHTS                          |                   |  |  |

FROM:

LIVINGSTON SPT CENTER  
5589 E M-36 CHILSON RD  
LAKELAND MI 48143

SHIP TO:

LIVINGSTON SPT CENTER  
5589 E M-36 CHILSON RD  
LAKELAND MI 48143

|                |                    |                                |            |            |           |            |
|----------------|--------------------|--------------------------------|------------|------------|-----------|------------|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED | VIA<br>UPS |
|----------------|--------------------|--------------------------------|------------|------------|-----------|------------|

|               |     |           |     |             |       |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION:

☒ LIKE NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARR'D

CUSTOMER'S REQUEST

*Customer tells me that on three separate occasions that gun has fired when safety was moved to the fire position.*

*No fault found - cannot duplicate complaint. Trigger assembly and safety function properly. Trigger pull somewhat heavy at 6#, semi-light at 8#.*

|       |                                                                                                                                                                            |       |       |      |        |         |
|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|-------|------|--------|---------|
| PARTS | <i>Offer to return rifle as-is or, if it will better restore faith in the rifle we will install a new trigger assembly at 1/2 normal price, as a gesture of good-will.</i> |       |       |      |        |         |
|       | REPAIRMAN<br><i>[Signature]</i>                                                                                                                                            | PROOF | CLEAN | TEST | TARGET | PATTERN |
|       | GALLERY TESTER                                                                                                                                                             | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV. 7.

PPS 03028