

RECEIVING AND ESTIMATING REPORT

COMMENTS

*To Product Service*ORDER
R 93-28682INITIAL
JJMCUSTOMER ORDER NO.
4970*XO Fi Supply*DATE RECEIVED
12/16/93DATE OPENED
12/21/93DATE CODE
PU 6-71SERIAL NUMBER
6444313

NEW SERIAL NUMBER

MODEL AND GRADE
700 270

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

LONGACRES
358 CHESTNUT ST
ABILENE

TX 79602

SHIP TO:

LONGACRES
358 CHESTNUT ST
ABILENETX
79602

CUST NO: 006401 ILION L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UFS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

E5

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT

Gun mfg. 6-71 Unable to duplicate customer concern as a Bottom of BBL and receiver (under stock) lightly rusted, rust on trig ASSY. (screws & side plates) Exchange trigger Assy at a special price as a gesture of good will - clean action - test and return

PARTS

COMMENTS

Action is dirty and gummy. Stock inletting area.

install trigger Assy clean &

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTE

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD8925 REV

PPS 03075