F.S.

# RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 94-15230

| INITIAL | CUSTOMER ORDER NO. |
|---|---|
| FPS | |

| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
|---|---|---|---|---|---|
| 05/06/94 | 05/09/94 | PH 6-87 | B6837357 | | 700 30-06 ADL |

ACCESSORIES W/STUDS

L/REAR SIGHT

FROM:

MENZIES, SCOTT
8 MANOR PLACE
HUNTINGTON STATION NY117-46

SHIP TO:

MENZIES, SCOTT
8 MANOR PLACE
HUNTINGTON STATION
NY117-46

CUST NO:097052 D.O.D

| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE | PROM. DATE | ESTIMATED | VIA |
|---|---|---|---|---|---|
| | | ☐ | | | UPS |

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

| | |
|---|---|
| REPAIR CHARGE | 20.00 |
| EXCISE | |
| TAX | |
| INSURANCE | |
| UPS | |
| PARCEL POST | |
| TOTAL | |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|---|---|---|---|---|---|---|
| CYCLE | A1 | B1 | | | | |
| TRIGGER GROUP ✓ | | B2 | | | | |
| BOLT ASSY. | | B3 | | | E2 | F2 |
| BARREL ASSY. | | B4 | | | E3 | F3 |
| REC. ASSY. | | B5 | | D2 | E4 | F4 |
| WOOD | | | C1 | D3 | E5 | F5 |
| METAL | | | C2 | | | |

When I cycled the safety button to fire, it fire without pulling trigger, cannot open bolt

MAIN FAULT Upon cycling bolt opens and closes but due to wear in sear and firing pin threads. Could not repeat cause of firing when the safety was released. Geometries of sear wear on bent, sear, and trigger assy. Sear engagement seems has been reset after worked from lack of maintenance

PARTS Firing Pin - 5/2 lb Bent Sear

#26345 Trigger Assy

COMMENTS Replaced trigger assy, tested when action at 1/2 normal operation 100% as gesture of good will.

| REPAIRMAN | PROOF | CLEAN | TEST | TARGET | PATTERN |
|---|---|---|---|---|---|
| TAL | | ✓ | ✓ | | |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |

JK

OFFICE COPY RD6925 REV. 1/94

to A/S 5/9/94