

3-3 150-
159

P.I. YES GUN EXAMINATION REPORT NUMBER: 97 MODEL: 700 BDL

GENERAL CONDITION: GOOD R #: 10136

OUTSIDE WORK: NONE DATE: 3-20-79

HPSTEVE MOORE
FROM: 6206 WASTCH WAY
SACRAMENTO CA.

FIRE AMMO TYPE: NOT KNOWN GUN #: A6366661

& CONDITION: — CODE: E-1-10-76

PROOF: (R/P) INSP.: 45 TEST: 97 GA./CAL.: 7MM

HEADING: OK CHECKED BY: M-HARDY

BREECH OPENING: OK APPROVED: SM 5/17/79

RECOIL SHOULDERS: OK APPROVED: RE 5/17/79

CHAMBER: OK APPROVED: E/B 5-17-79

TEST: — APPROVED: 5/17/79

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 5/17/79

SLIGHT SCRATCHES ON STOCK REC. MAR. TOP
AND LEFT SIDE. FLOOR PLATE BRIGHT SPOTS

COMPLAINT: Gun damaged inside cab of truck.

INCIDENT: —

COMMENTS: Unable to duplicate customer complaint.

- Trigger free - no bind.
- 2.5% passed truck test.
- Trigger Pull 5#