

RECEIVING AND ESTIMATING REPORT

COMMENTS

*To Product Service,*ORDER
R 94-06401INITIAL
FPSCUSTOMER ORDER NO.
52035DATE RECEIVED
02/15/94DATE OPENED
02/21/94DATE CODE
RU 11-71SERIAL NUMBER
6501964

NEW SERIAL NUMBER

MODEL AND GRADE
700 243

ADL

ACCESSORIES

L/SIGHTS

SCOPE BASE

FROM:

SHIP TO:

NAGELS GUN SHOP
6201 SAN PEDRO AVE
SAN ANTONIO

TX 78216

NAGELS GUN SHOP
6201 SAN PEDRO AVE
SAN ANTONIOTX
78216

CUST NO: 006582 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

REPAIR CHARGE 20.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

G1

METAL

C2

MAIN FAULT

Gum mfg. 4/71 Unable to duplicate customer concern as rec'd. Barrel and receiver have rust spots. Connector is lightly rusted. Trigger Assy. has excessive lubrication in it. Inside of housing and trigger are gummed up 'SHELLAC LIKE SUBSTANCE'. POOR MAINTENANCE. Clean Action and install TRIGGER ASSY. at special price strictly as a gesture of good will.

PARTS

TRIGGER ASSY.

COMMENTS

Trigger pull measured at #5 as Received.

BERNARD

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

FD5925 REV. 1/94

PPS 03609