

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-16548

INITIAL CUSTOMER ORDER NO.

JJM 6012

ATTN JACK KAST
BBL CHANGED OUTSIDE FACTORY

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/24/94

05/24/94

B6469332

700 280

BDL/LH

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

ON TARGET INC
6984 W MAIN ST
KALAMAZOO

MI 49009

ON TARGET INC
6984 W MAIN ST
KALAMAZOO

MI
49009

CUST NO: 002454 WELM

ACCOUNT NUMBER

ACCOUNT NUMBER NYC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☒ NEW

☐ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

When receipt was made unable to duplicate the customer concern. Examination did not find the problem on the trigger adjustment screw. The trigger pull measured 3.5 lbs. min. spec. Action much better.

ARTS

San diego - 014

COMMENTS

#26345 Trigger Assembly

Revised trigger assembly and then action at 1/2 normal speed. Cost as given & good unit.

Go ahead to A/S 5/24/94

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/9

PPS 03702