

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-11932

CUSTOMER ORDER NO.
JB 9479

ATTN DENNIS SANITA L/ STUDS
SIDE OF REC TAPPED

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
4/04/94	04/06/94	XA 12-B0	B6285745		700 270 BDL

DM:

SHIP TO:

OUTDOOR SPORTSMAN INC
1206 HIGHWAY 31 S
ATHENS

AL 35611

OUTDOOR SPORTSMAN INC
1206 HIGHWAY 31 S
ATHENS

AL
35611

CUST NO: 035006 C.M.D.L

COUNT NUMBER	ACCOUNT NUMBER N/C 059015	PROM. DATE	ESTIMATED	VIA UPS
CONDITION	REPAIR CHARGE			
NEW	EXCISE			
LIGHTLY WORN	TAX			
WORN	INSURANCE			
VERY WORN	UPS			
UNREPAIRABLE	PARCEL POST			
MARRED	TOTAL			

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	<i>Firing pin was released when safety was taken from on to off position after cleaning</i>				
GGER GROUP						
LT ASSY.						
RREL SY.						
C. ASSY.						
XOD						
TAL			C1	D1	E1	F1
			C2	D2	E2	F2
				D3	E3	F3
				D4	E4	F4
				D5	E5	F5

VF FAULT *Mfr. 12-80 Unable to duplicate customer concern as recd. Trigger performed normally with all checks. Trigger Ass appeared to be in good working order with light lubrication and no debris on just. Exchange trigger Assy. at N/C as a gesture of good will and to restore customer confidence in the gun.*

ITS	COMMENTS <i>Trigger pull measured 5 1/2 LBS as Rec'd. Gun engagement was OK</i>																	
<table border="1"> <tr> <td>REPAIRMAN <i>JB</i></td> <td>PROOF</td> <td>CLEAN ✓</td> <td>TEST ✓</td> <td>TARGET</td> <td>PATTERN</td> </tr> <tr> <td>GALLERY TESTER</td> <td>DATE</td> <td>DATE</td> <td>DATE</td> <td>DATE</td> <td>DATE</td> </tr> </table>							REPAIRMAN <i>JB</i>	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE
REPAIRMAN <i>JB</i>	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN													
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE													

OFFICE COPY

RO6925 REV. 1/94

PPS 03731