

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-11942

INITIAL

CUSTOMER ORDER NO.

J.J.M.

DATE RECEIVED

05/14/93

DATE OPENED

05/18/93

DATE CODE

AI 3-76

SERIAL NUMBER

A6283372

NEW SERIAL NUMBER

MODEL AND GRADE

700 25-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

OWENS, ROBERT K
RT 2 BOX 56H
CEDAR BLUFF

VA 24609

SHIP TO:

OWENS, ROBERT K
RT 2 BOX 56H
CEDAR BLUFFVA
24609

CUST NO: 079242 C.D.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Upon receipt trigger function inspection. Examination revealed that when bolt was closed, the firing pin would follow down. Call 3 trigger adjustment / Engagement screws have been tightened with outside the factory. They were also checked out & the result was good. Action has been given added to what.

Rept May 1976
Trigger Part - 4/12/86
Screw Bolt - 006

Rept trigger assembly complete at 1/2 normal replacement cost and clear action is faster & good well

PARTS

COMMENTS

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/87

PPS 03747