

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-03077

INITIAL CUSTOMER ORDER NO.

W/LEUPOLD 2X7 SCOPE & SEE THRU SCOPE MNTS

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/17/92

01/24/92

WI

A6346902

700 30-06

ADL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

PAYNE, CLAYTON L
1360 GIBSON DRIVE
BIRMINGHAM

AL 35214

PAYNE, CLAYTON L
1360 GIBSON DRIVE
BIRMINGHAMAL
35214

CUST NO: 056921 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1	2 times, fired when safety released			
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Cannot duplicate complaint after many attempts.
Removal of barrel action from stock prevented shot of cleaning gel
on underside of metal. Trigger assembly is extremely oily & dirty
also.

Trigger pull 3 3/4 pounds; var. left .007"

PARTS

COMMENTS

Efforts to clean present trigger assembly
if possible. If not, offer to replace
trigger assembly at a reduced cost,
as a gesture of good-will.

Return scope & mnt in cabinet

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PPS 03826