

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-12789

INITIAL

CUSTOMER ORDER NO.

FJB

CALL TAG DENNIS SANITA

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/12/94

04/13/94

A6346902

700 30-06

ADL

ACCESSORIES

W/STUDS

WI 8-762ND TIME IN

FROM:

SHIP TO:

PAYNE, CLAYTON L
1360 GIBSON DRIVE
BIRMINGHAM

AL 35214

PAYNE, CLAYTON L
1360 GIBSON DRIVE
BIRMINGHAMAL
35214

CUST NO: 056921 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

We found some corrosion. Action, trigger assembly, and bolt assembly covered with a very sticky substance. Trigger and bolt lubrication also noted. Called customer and removed our findings.

PARTS

TP - 4 1/2 lb
SL - .04

Replaced trigger assembly

COMMENTS

Agreed to return as a gesture of good will. replace complete trigger assembly and clean action.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		☒	☒		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 03832