

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS W/1 STUD ONLY			
DATE RECEIVED 10/17/89	DATE OPENED 01/28/89	DATE CODE BU 1-71	SERIAL NUMBER 6392261	MODEL AND GRADE 600 243	MOHAWK	ORDER R 89-03896	
ACCESSORIES SCOPE BASE							

FROM:	SHIP TO:
JAMES R. PERRIGO Z MALONE PLUMBING & HEATING ELM STREET RD. MALONE, N.Y. 12953	JAMES R. PERRIGO Z MALONE PLUMBING & HEATING ELM STREET RD. MALONE, N.Y. 12953
ACCOUNT NUMBER	ACCOUNT NUMBER N/C
WRITE ☐	PROM. DATE ESTIMATED VIA UPS

DEAR CUSTOMER:
WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED					
CUSTOMER'S REQUEST					

MAIN FAULT	
PARTS	
<i>Begin Part - 5.20</i> <i>End Part - 0115</i>	

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD923 REV. 4/84