

RECEIVING AND ESTIMATING REPORT

CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
9-86	B6735295	700 7MMHAG EDL	R 88-05101

L7SIGHTS

FALSE RIVER SPORTS SHOP, INC.
211 W. MAIN ST.
NEW ROADS, LA.

79760

SHIP TO:

FALSE RIVER SPORTS SHOP, INC.
211 W. MAIN ST.
NEW ROADS, LA.

70760

INSTRUMENT NUMBER	TAX ST	INSURANCE	FROM DATE	ESTIMATED	VIA
40.00				2-26-88	UPS
REPAIR CHARGE	TAX CITY	UP	PARCEL POST	TOTAL	
		4.09		\$ 44.09	

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☒ QUOTE

CUSTOMER'S COMPLAINT

"...when I pushed the safety forward, the rifle went off..."

MAIN FAULT

Trigger currently is full of rust of camo paint - assembly is so full of rust of paint that the trigger will not consistently return under rear safety cam on cocking. Rifle has been very poorly maintained.

DEMERIT CODE

PARTS

Send repair quotation to repair as necessary.

2/25/88

JLB

FOR COMPUTER REF. ONLY

PROOF

CLEAN TEST TARGET

REPAIRMAN

OFFICE COPY

REV. 3/84