

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS TRIGGER ASSEMBLY ONLY	
DATE RECEIVED 12/27/90	DATE OPENED 01/03/91	DATE CODE	SERIAL NUMBER 99985364	MODEL AND GRADE 700	ORDER R 91-0027
ACCESSORIES					

FROM:

REESE, JOE
2695 W 5TH STREET
YUMA

AZ 85364

SHIP TO:

REESE, JOE
2695 W 5TH STREET
YUMA

AZ
85364

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	FROM DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Repair or replace trigger assembly which malfunctions (see letter)

MAIN FAULT

Trigger assembly adjusted outside factory, therefore cannot replace for customer at no chg. (see RHP reply attached)

PARTS

Disposition - 1/29/91 RHP

Scrap trigger assy & take no further action.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD4725 REV. 7/90