

RECEIVING AND ESTIMATING REPORT

M93-17685

INITIAL	CUSTOMER ORDER NO.	W/PACHMAYR RECOIL PAD			
FPS	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER
	08/20/93	08/25/93	84	B6626691	
ACCESSORIES	SCOPE BASE		MODEL AND GRADE		
			700 270 WIN ADL		

FROM:

SHIP TO:

SATIN SEAR PISTOLSMITH
424A PECAN DR.
ALEDO TX 76008

SATIN SEAR PISTOLSMITH
424A PECAN DR.
ALEDO TX 76008

CUST NO: 082651 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				9-9-93	UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			☐ EXCISE ☐ TAX ☐ INSURANCE ☐ UPS ☐ PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL						

MAIN FAULT

Unable to disassemble without damage. However, disassembly revealed that all 3 adjustment screws have had the correct amount, indicating they have been tampered with without the proper knowledge of the correct way to adjust them. In a word, they are bad. All in all, the gun is a good one.

PARTS

COMMENTS

Repaired trigger assembly at the same adjustment and in spirit of good will.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	P/
C.C.					
GALLERY TESTER	DATE	DATE	DATE	DATE	D

OFFICE COPY

RD6925