

Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 RDL
 GENERAL CONDITION: NEW R #: 24852
 OUTSIDE WORK: No DATE: 11-9-70
 FROM: SHAFF HDWE.
 FIRED AMMO TYPE: — PALMERTON, PA.
 & CONDITION: _____ GUN #: 6311069
 PROOF: R.E.P. INSP.: 74 ASSEM. 79 TEST: _____ CODE: BT = 1/70
 HEADING: O.K. GA./CAL.: 3006
 BREECH OPENING: — CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

PARTS O.K.

COMPLAINT: "EVERY TIME YOU PUSH THE BOLT HARD THE
RIFLE FIRES."

INCIDENT: FOLLOWS DOWN

COMMENTS: THE ENGAGEMENT OF THE SEAR, TRIGGER CON-
NECTOR SET TOO CLOSE AT FINAL ASSEMBLY. (005P)