

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS		ORDER	
R		1382		L SIGHT ON REAR BASE		89-06343	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE			
02/01/89	02/17/89	DY 9-74	6779694	700 308 BDL			
ACCESSORIES		SCOPE BASE					
W/STUDS							

FROM:	SHIP TO:
SHOEMAKERS INC (PRO)	SHOEMAKERS INC (PRO)
763 SOUTH SECOND ST	763 SOUTH SECOND ST
CHAMBERSBURG PA 17201-0000	CHAMBERSBURG, PA 17201-0000

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA
					UPS

DEAR CUSTOMER:
 WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

PARTS

REPAIRMAN	PROOF	CLEAN	TEST	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY

800925 REV. 6/88