

RECEIVING AND ESTIMATING REPORT				COMMENTS <i>to product service</i>		ORDER R93-24470	
INITIAL	CUSTOMER ORDER NO.			MAGNA-PORTED W/SEE THRU SCOPE MNTS			
FPS							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
11/08/93	11/12/93	EQ 10-78	A6674932		700 30-06		BDL
ACCESSORIES		HARD CASE					
L/STUDS				<i>XC Full Supply</i>			
FROM:				SHIP TO:			
TROCHTA, SABRA HC 68 BOX 121 A KINGSTON				TROCHTA, SABRA HC 68 BOX 121 A KINGSTON			
OK 73439				OK 73439			

ACCOUNT NUMBER		ACCOUNT NUMBER N/C		CUST NO: 087183 C.O.D		PROM. DATE	ESTIMATED	VIA
		<i>059015</i>						UPS
GUN CONDITION		WRITE ☐						REPAIR CHARGE
☐ NEW ☒ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED								EXCISE
								TAX
								INSURANCE
								UPS
								PARCEL POST
								TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	11	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Unable to duplicate customer concern. Examination revealed
 fault on trigger assembly from unknown source, & state
 as cracked at rear of trigger guard*

PARTS	COMMENTS
	<i>Repaired shot receiver</i>
	<i>Repaired trigger assembly</i>
	<i>Completed, and then tested</i>
	<i>Left mfg 1978, lightly worn, and</i>
	<i>used for</i>
REPAIRMAN	PROOF
<i>RA</i>	<i>✓</i>
GALLERY TESTER	DATE
CLEAN	TEST
<i>✓</i>	<i>✓</i>
TARGET	PATTERN

OFFICE COPY