

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		COMMENTS			
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
9/91	01/15/91	XS 12-69	6210107	660 308	R 91-01421
PRIES W/STUDS					

SHIP TO:

VERSER, RONALD
30 HARVER HILLS
MALVERN AR 72104

VERSER, RONALD
30 HARVER HILLS
MALVERN AR 72104

L	J	L
ITEM NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST
		PROM. DATE ESTIMATED VIA
		1-24 UPS

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

REPAIR REQUEST *Rifle mechanism & while chambering a round*

JLT *Rifle cannot be made to function. Target and sight assembly is damaged. Target full 5th, can't hit .0065" over, sight is subject to target assembly recall.*

Replace trigger assembly at no-charge under recall provision.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
TS 107					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE