

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
94-14433INITIAL
FPS CUSTOMER ORDER NO.CALL TAG ATTN: DENNIS SANITA
W/BTH. PART OF SEE THRU SCOPE MNTS

DATE RECEIVED 04/27/94	DATE OPENED 04/28/94	DATE CODE DV 9-79	SERIAL NUMBER A6813397	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL
---------------------------	-------------------------	----------------------	---------------------------	-------------------	------------------------------	-----

ACCESSORIES
W/STUDS

FROM:

VOLPE, STEPHEN R.
1017 GREEN GLEN DRIVE
DEBOIS PA 15801

SHIP TO:

VOLPE, STEPHEN R.
1017 GREEN GLEN DRIVE
DEBOIS PA 15801

CUST NO: 096641 G.L.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B5

REC. ASSY.

C1

WOOD

C2

METAL

MAIN FAULT

Upon receipt we would not suspect customer concern. Bolt stop
 working slightly, explanation revealed that the action is correct with gun
 slightly out of time. Bottom of trigger assembly and main trigger housing
 covered with dirt. Right hand trigger assembly. Trigger assembly 1/2 in.

PARTS

COMMENTS

Replace complete trigger assembly &
 clean action at 1/2 normal cost as
 per the order will
 go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

FD-6925 REV. 1/94