

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATT DICK ST JOHN/L REAR SIGHT

INITIAL CUSTOMER ORDER NO.

B 1338

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

01/09/89

01/18/89

CA 4-80

B6203109

700

300

BDL/MAG

R

89-02258

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

WILLIAMSON-PATE GUNSMITH SERVI
DBA/GUNCRAFT, INC (PRO
117 W PIPELINE ROAD
HURST, TEXAS

000076053

SHIP TO:

WILLIAMSON-PATE GUNSMITH SERVI
DBA/GUNCRAFT, INC (PRO
117 W PIPELINE ROAD
HURST, TEXAS

000076053

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

DEAR CUSTOMER:

WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

MAIN FAULT

PARTS

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD4923 REV. 4/88