

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047196 Account # - R-	Description/Serial Number 6607904 Model 700 Center Fire Caliber: 270 BDL	Date Received - 6/12/2002 Estimate Date - 6/11/2002 Current Date - 7/9/2002
Customer ACCUFLITE ARMS 5120 OLD WILLIAM PENN HWY EXPORT. PA 15632 US Phone (H) (724)-733-3666 Phone (W)	Return To ACCUFLITE ARMS 5120 OLD WILLIAM PENN HWY EXPORT. PA 15632 US Fax (724)-733-7033 Email accuflite@usaor.net	

Problems			
Reported		Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE FO
		M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	forward to product service for inspection bolt look modification clean and inspect replace trigger FLS

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	22	


13 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

ACCUFLITE ARMS
5120 OLD WILLIAM PENN HWY
EXPORT PA 15632




PA 156 9-10



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 7112



BILLING: P/P

INV#: RE00047196

ASC 05.00 J69X/J64X 16.0A 01/2002