

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-16166

VITAL CUSTOMER ORDER NO.

JJM 13078

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/18/94

05/19/94

DY 9-74

6788700

700 30-06

ADL

ACCESSORIES

SCOPE BASE

FROM:

SHIP TO:

AHLMANS
RTE 1 BOX 20
MORRISTOWN

MN 55052

AHLMANS
RTE 1 BOX 20
MORRISTOWNMN
55052

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 002719 WILM

FROM DATE

ESTIMATED

VIA

WRITE ☐

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

GUN IN FAULT

May 9-74 Unable to find anything wrong by cycling action and making safety off for numerous times. Trigger and connector were rusty. Exchange trigger assy. at a special price as a gesture of good will. Recommended that all metal parts be maintained with a light film of light oil.

RTS

COMMENTS

Trigger Assy Complete
with Bolt Lock

Trigger pull measured 4 3/4 to 5 1/4
as rec'd. rear lift was .011

Some rust on underside of Receiver

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

FD6925 REV. 1/94

PS00381

13078

TO: Rom.

This firearm has the following defect: Gun fires
by itself

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morristown, MN 55052

RETURN POSTAGE GUARANTEED