

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00048698 Account # - R-	Description/Serial Number 6560825 Model 700 Center Fire Caliber: 7 MM MAG BDL	Date Received - 6/26/2002 Estimate Date - Current Date - 7/9/2002
Customer J AND J GUIDE SERVICE 213 COPENO STREET PORT MANSFIELD, TX 78598 US		Return To J AND J GUIDE SERVICE 213 COPENO STREET PORT MANSFIELD, TX 78598 US
Phone (H) (956)-944-2639 Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO
M992	GUN DISCHARGED WHILE BEING UNLOADED		

Technician's Comments	
ProblemNotes	Per agreement with customer, clean action and install new style trigger assembly at n/c. Trigger assembly extremely gummy. FLS 6/26/02.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
Service	Total:	2	


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

J AND J GUIDE SERVICE
213 COPENO STREET
PORT MANSFIELD TX 78598




TX 785 0-01



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 6462



BILLING: P/P

INV#: RE00048698

ASC 05.00 J69X/J64X 16.0A 01/2002