

RECEIVING AND ESTIMATING REPORT

COMMENTS

*To Product Service*ORDER
R 94-37443INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
12/19/94DATE OPENED
12/28/94DATE CODE
WL 8-91SERIAL NUMBER
C6666539

NEW SERIAL NUMBER

MODEL AND GRADE

700 7MMAG

BDL/LH

ACCESSORIES

W/STUDS

FROM:

ANGLERS ROOST
1277 S BROAD ST

SUMMERSVILLE

WV 26651

SHIP TO:

ANGLERS ROOST
1277 S BROAD ST
ATTN JAMES F HALSTEAD
SUMMERSVILLE

WV

26651

CUST NO:007168 ILIONL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059001

WRITE ☐

FROM DATE

ESTIMATED

1-22

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

*1/23/95**Large ding at end of fore-end checking as recd.*

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

Shoves brass, fired with safety on

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

After 8-91 Unable to make gun fire with safe on. Only way gun could be made to fire was with safe off and trigger pulled. Exchange trigger assy at life due to main seal engagement.

PARTS

COMMENTS

Trigger pull measured 3 3/4 to 4 1/4 #5 on recd. seal lift was .0135 Seal engagement was .004 under spec.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTER

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/7

PS00677