## Kemington.

## TRACKING DOCUMENT

## **Repair Order Number**



Repairman -

Estimate Date -

Date Received · 12/18/2003

Current Date - 12/22/2003

Herb Brown

Repair Order Number

RE00074147

Description/Serial Number

6352608

Account # - R-

Customer

BILL ANTON

Model 700 Center Fire with 22 inch

barrel Caliber: 3006 ADL L/BUTT

**PLATE** 

Return To

**BILL ANTON** 

10016 FERNHAVEN COURT

BEVIS, OH 45251 US

10016 FERNHAVEN COURT

BEVIS, OH 45251 US

Phone (H)

Phone (W)

Fax <u>Email</u>

FORWARD TO PRODUCT SERVICE

FOR INSPECTION

M990

M123

**BOLT STOP BROKEN** 

M123 FORWARD TO PRODUCT SERVICE FOR

Material #	<u>MaterialDesc</u>	Quantity	<u>Quantity</u>	<b>Quantity</b>	<u>Warranty</u>
		<u>Needed</u>	From Inv	From Kit	<u>(Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part	Total:	1	1	0	
Service			•		
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	. 1	1	0	Υ .
Service	Total:	2	2		·

Problems

**ProblemNotes** 

Upon receipt we could not duplicate the reported concern. Action and trigger assm. covered with sticky substance. Parts moving very slugish, poor maintenance. Clean action and replac trigger

assm. at no charge.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date