

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-24177INITIAL
JJM

ATTN JACK KAST

DATE RECEIVED
08/19/94DATE OPENED
08/22/94DATE CODE
DN 9-66SERIAL NUMBER
242504

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

ADL

CESSORIES

FROM:

SHIP TO:

ATLANTIC & PACIFIC ARMS CO
4859 VIRGINIA BEACH BLVD
VIRGINIA BEACH VA 23462ATLANTIC & PACIFIC ARMS CO
4859 VIRGINIA BEACH BLVD
VIRGINIA BEACH VA
23462

CUST NO: 007045 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Gun found when taking safety off - gun was purchased used and stored for about 15 years.

After 9/66 unable to duplicate customer concern as noted. - Bottom of receiver and bbl. were covered with hardened 'solidified' lubricant, inside of trigger housing 'both sides' had rust as well as on trigger. Exchange trigger assy. at a special price as a gesture of good will.

PARTS

COMMENTS

trigger pull measured 4 to 4 1/4 lbs as recd. Break lift was .008

Some rust on bbl. at stock pressure Fed and spots of rust on receiver underside.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS00830