

RECEIVING & ESTIMATING REPORT

CUST NO: 620426 G.O.D

INITIAL: JJM CUSTOMER ORDER NO.

DATE RECEIVED: 08/21/91 DATE OPENED: 08/23/91 DATE CODE: BZ 1-75 SERIAL NUMBER: 6829623 MODEL AND GRADE: 700 22-250 BDL ORDER: R 91-16576

ACCESSORIES: W/STUDS SCOPE BASE L/REAR SIGHT

FROM: BIG JOHN'S GUNS & SUPPLIES 1508 HOUSTON NEDERLAND TX 77627 USA
SHIP TO: BIG JOHN'S GUNS & SUPPLIES 1508 HOUSTON NEDERLAND TX 77627 USA

ACCOUNT NUMBER: ACCOUNT NUMBER N/C: WRITE ☐ CLEAN/TEST PROM. DATE: ESTIMATED: VIA: UPS



REPAIR CHARGE: TAX: INSURANCE: UPS: PARCEL POST: TOTAL:

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED.

CUSTOMER'S REQUEST: Fires when closing bolt also, complaining of headspace problem.

MAIN FAULT: Cannot duplicate fire on closing complaint. However, trigger assembly has been improperly adjusted outside factory, as evidenced by non-Remington sealant on adjustment screws - 1) insufficient overtravel 2) insufficient seal engagement. Trigger pull 4 1/2 lbs. seal-off 00075".

PARTS: 1) Check for headspace
2) Send repair quote for new trigger assembly at 1/2 normal cost, as gesture of good-will

REPAIRMAN: HB	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE