

|             |  |               |  |             |  |           |  |               |  |                 |  |            |  |
|-------------|--|---------------|--|-------------|--|-----------|--|---------------|--|-----------------|--|------------|--|
| JJM         |  | DATE RECEIVED |  | DATE OPENED |  | DATE CODE |  | SERIAL NUMBER |  | MODEL AND GRADE |  | ORDER      |  |
| 09/16/91    |  | 09/19/91      |  | EO 10-77    |  | A6440949  |  | 700 270       |  | ADL             |  | R 91-18470 |  |
| ACCESSORIES |  |               |  | W/STUDS     |  |           |  | SCOPE BASE    |  |                 |  |            |  |

|                                                                                                    |                                                                                                    |
|----------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|
| FROM:                                                                                              | SHIP TO:                                                                                           |
| BEDFORD, DAVID<br>500 NORTH WATER SUITE 400<br>CCNB CENTER NORTH<br>CORPUS CHRISTI TX 78471<br>USA | BEDFORD, DAVID<br>500 NORTH WATER SUITE 400<br>CCNB CENTER NORTH<br>CORPUS CHRISTI TX 78471<br>USA |

|                |                    |                                |            |            |           |     |
|----------------|--------------------|--------------------------------|------------|------------|-----------|-----|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED | VIA |
|                |                    |                                |            |            | 9/15/91   | UPS |

|               |     |           |     |             |       |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: "I moved the safety to the 'on' position and moved the bolt only about 1/2", the firing pin released..."

MAIN FAULT: Unable to duplicate complaint - many attempts were made to reproduce the above complaint, using dummy ammunition in the chamber - no malfunctions were experienced. The trigger safety assembly operates normally. Trigger pull measured at 5#

PARTS: Offer to return rifle as-is as is, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, & it will better restore confidence in the rifle

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| LGZ            |       |       |      |        |         |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |