

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047952 Account # - R-	Description/Serial Number B6434369 Model 700 Center Fire Caliber: 2506 BDL W/ SCOPE	Date Received - 6/11/2002 Estimate Date - Current Date - 6/19/2002
Customer C J CAUDILL 75 E MAIN ST MOHAWK. NY 13407 US Phone (H) (315)-866-9678 Phone (W)	EMPLOYEE 	Return To C J CAUDILL 75 E MAIN ST MOHAWK. NY 13407 US Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO

Technician's Comments	
Condition	REC'D W/ WOOD DINGS & MARS ON TRIG GUARD. BBL MARS NEAR MUZZLE.
Problem/Notes	Covered with sticky substance/dirty. Parts working sluggish. Replace complete trigger assembly, for \$20.00 poor maintenance per DJS.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	22	