

Date: 11/9/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: City of Cin.

R.E. Number: 103307

Reason for inspection: FBC

FIREARM

Manufacturer: Rm Model: 700

Serial Number: D6276105 Date of Manufacture: 1/99

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: —

Headspace: —

Function evaluation:

Feeding:

Extraction/ejection:

Trigger pull: 3.5#

Manual safety: OK

Test firing results (if applicable):

DISPOSITION

could not duplicate concern. Replace TPA to
restore confidence. Set Trig pull to min specs AT N

ADDITIONAL COMMENTS

#230145