

RECEIVING AND ESTIMATING REPORT

TITLE		CUSTOMER ORDER NO.		COMMENTS	
PS					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
4/24/91	04/25/91	LI 2-88	C6231502	700 308 WIN POL	R 91-09844
ACCESSORIES		SCOPE BASE			
W/STUDS					

FROM: TPR. DYWINSKI, LEON SFI NEW YORK STATE POLICE 4525 W SAILE DR BATAVIA NY 14020	SHIPTO: TPR. DYWINSKI, LEON SFI NEW YORK STATE POLICE 4525 W SAILE DR BATAVIA NY 14020
---	---

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION:

NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ **MARRIED**

CUSTOMER'S REQUEST

CUSTOMER'S REQUEST "When the safety is on the bolt is able to be cocked. When the safety is released the firing pin goes forward".

SIN FAULT

As received, the firing pin followed-down when the bolt was closed. Disassembly revealed the trigger assembly was seated from unknown cause, causing the internal trigger parts to not move freely.

RTS

Replace trigger assembly at no charge
as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
ALLERT TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6825 REV. 7/90

PS01639