

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

www.remington.com info@remington.com

Fax

336-548-7801

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00050052 Account # - R-	Description/Serial Number A6639666 Model 700 Center Fire Caliber: 270 BDL	Date Received - 8/6/2002 Estimate Date - 8/5/2002 Current Date - 8/9/2002
Customer ROGER DAVISSON 209 PLAINFIELD AVE P.O. BOX 278 ANMOORE, WV 26323 US	Return To ROGER DAVISSON P.O. BOX 278 ANMOORE, WV 26323 US	
Phone (H) (304)-203-3969 Xcell Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO
M240	BOLT LOCK SAFETY MODIFICATION		
M993	WANTS A SERIAL NUMBER WITHOUT SIXES		

Technician's Comments	
Condition	Rec'd w/ minor wood dings.
Problem/Notes	action and trigger assm covered with dirt and heavy sticky substance. poorly maintained. replace trigger assm complete at \$20.00

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
Service Total:		21	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

ROGER DAVISSON
209 PLAINFIELD AVE
ANMOORE WV 26323




WV 263 2-01



UPS GROUND

TRACKING #: 1Z 114 813 03 1192 2257



BILLING: P/P

INV#: RE00050052

ASC 05.00 J69X/J64X 16.0A 01/2002