

RECEIVING AND ESTIMATING REPORT

COMMENTS

Provision Service

ORDER R 94-21443

CUSTOMER ORDER NO.

JM

RECEIVED 7/18/94 DATE OPENED 07/19/94 DATE CODE DN 7-93 SERIAL NUMBER C6810369 NEW SERIAL NUMBER MODEL AND GRADE 700 7MMMAG BDL

SSORIES W/STUDS SCOPE BASE L/REAR SIGHT

Set up file

A:

DAVES SPORT SHOP INC
RTE 1 BOX 66
QUANTICO

MD 21856-9710

DAVES SPORT SHOP INC
RTE 1 BOX 66
QUANTICO

MD 21856-9710

CUST NO 002302 WILM L

QUANTITY

ACCOUNT NUMBER N/C

055015

WRITE ☐

PROM. DATE

ESTIMATED

8-8-94

VIA

UPS

CONDITION

NEW

SLIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

DAMAGED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
TRIGGER GROUP		B2			E1	
TRIGGER ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
DD			C1	D3	E5	F5
AL			C2			

FAULT *Mfg. 7/93 Unable to duplicate customer concern as recd. Disassembled trigger Assy could find no fault, trigger functioned correctly in every respect. Exchange trigger Assy as a gesture of good will and to restore customers confidence in rifle. Customer may have inadvertently pulled on trigger when releasing safety.*

S *Trigger Assy Complete* COMMENTS *Trigger pull measured 4.4 to 5.1 lbs as recd and rear lift was .016*

De burr ejector plunger hole

REPAIRMAN *RRS* PROOF CLEAN ☒ TEST ☒ TARGET PATTERN

GALLERY TESTER DATE DATE DATE DATE DATE

OFFICE COPY

RD6925 REV 1/94

PS01915