



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00057607	Description/Serial Number 220765	Repairman - Richard Hilts Date Received - 12/16/2002
Account # - R-	Model 721 Center Fire Caliber: 270	Estimate Date - Current Date - 12/31/2002
Customer LEONARD DALMAS 205 CRAGLE HILL RD SHICKSHINNY. PA 18655 US	Return To LEONARD DALMAS 205 CRAGLE HILL RD SHICKSHINNY. PA 18655 US	
Phone (H) Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 M239	FORWARD TO PRODUCT SERVICE FOR REPLACE TRIGGER ASSEMBLY

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

Condition	BOLT MARRED @ OPENING BENCH. CUSTOMER HAD BASE SCREWS ALL THE WAY DOWN INTO REC W/O THE BASE.				
ProblemNotes	safety detent worn safety arm moves replace trigger assembly				
Repairman	Proof	Clean	Test	Target	Pattern
GALLERY TESTER	Date	Date	Date	Date	Date