

**Repair Order Number** 

## **TRACKING DOCUMENT**

Repair Order RE00069803	Number	Description/Serial Number A6801906			Repairman - Carl Cotton Date Received - 9/30/2003			
Account # - R-		Model 700 Center Fire Caliber: 308 WIN			<b>Estimate Date -</b> 9/16/2003			
		BDL			Current	<b>Date -</b> 10/9	9/2003	
Customer JRS HUNTI 310 E 15TH	NG AND SURPLUS ST	<b>Return To</b> JRS HUNTING AND SURPLUS 310 E 15TH ST						
YAZOO CIT	Y. MS 39194 US		. YAZOO CITY. MS 39194 US					
Phone (H) Phone (W)	(662)-673-9434         Fax         (662)-673-8161           Email         WEDGE@dixie-net.com						i 	
Reported M123 M240 M992	FORWARD TO PRO FOR INSPECTION BOLT LOCK SAFE DISCHARGED BY	DDUCT SERVICE	noblems M239 N		************************	IGGER ASS	EMBLY	
<u>Material #</u>	<u>MaterialDesc</u>				Quantity	<u>Quantity</u>		
Part			Nee	<u>ded</u> <u>F</u>	From Inv	<u>From Kit</u>	<u>(Y/N)</u>	
F26345 Part	700 TRIG ASSB RH Total:			<u> </u>	<u> </u>	<u> </u>	•	
Service 4000294 4000104 4000116 4000118 4000119 Service	GR-CHECK TPA ARMS SERV SHIPPI GR-LABOR GR-CLEAN GR-TEST <b>Total:</b>	NG & HANDLING		$     \begin{array}{c}       1 \\       0 \\       20 \\       1 \\       1 \\       23 \\     \end{array} $	1 0 20 1 1 <b>23</b>	0 0 0 0 0	Y Y N Y Y	
¢								
ProblemNotes Trigger assy. is covered with dust and dirt, poor maintainance. Also has the old style bolt lock safety. Quoted for cleaning and replacing the trigger assy. under the bolt lock safety program.								
Repairman	Proof	Clean	Test	Ta	irget	Patt	ern	
Gallery Tester	Date	Date	Date	Da	ate	Dat	e	