

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
SERVICE

ORDER
R 94-27524

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

09/26/94

09/28/94

LW 2-72

6523175

700 25-06

BDL/VAR

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

EL PASO GUN EXCHANGE
6250 EDMERE
EL PASO

TX 79925

EL PASO GUN EXCHANGE
6250 EDMERE
EL PASO

TX
79925

CUST NO: 006774 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00

8.00

28.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

11/24/94 Gun did slam fire once during examination. All 3 trigger adjusting screws have been altered outside of the factory. Not recommended. Exchange trigger assy. at a spec. price as a gesture of good will.

PARTS

COMMENTS

Trigger Assy Complete

Trigger pull measured 2 3/4 to 3 1/4 LBS at spec. See lift was .009

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS02253