RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN DENNIS SANITA

ORDER: R 94-06998

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/18/94	02/25/94	BI 1-88	C6214188		700 30-06 ADL

ACCESSORIES: SOFT CASE

FROM:
EERNISSE, WILLIAM J
1729 CYPRESS DRIVE
GRAFTON WI 53024

SHIP TO:
EERNISSE, WILLIAM J
1729 CYPRESS DRIVE
GRAFTON WI 53024

CUST NO:092976 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
	059001	☐			UPS

GUN CONDITION
- ☐ NEW
- ☑ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

While pushing the safety forward, the safe fired

MAIN FAULT: Upon accept, could not duplicate customer concern. However, examination revealed that more than normal force is required to move the safety. Slide is cocked at the mag. well area.

PARTS

COMMENTS: Replace complete trigger assembly and slide assembly at no charge.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.

to A/S 2/28/94

PS02264