

Date: 11/2/04
By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Mike Fairman
R.E. Number: 87324
Reason for inspection: FSR

FIREARM

Manufacturer: Rim. Model: 7
Serial Number: 7775242 Date of Manufacture: _____
Overall external condition: Good

Barrel condition: okay

Receiver condition: okay

Stock condition: chipped from/during installing after mkt. pod

Bolt/firing pin condition: okay

Trigger assembly condition:

Engagement: altered

Adjustments/alterations: altered

Other: —

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 2.5th

Manual safety: okay

Test firing results (if applicable): _____

DISPOSITION

Trig. pull screw adjusted beyond length of return
'spr. not allowing proper return of trig. replace

ADDITIONAL COMMENTS

Trig. oasm. at N/C under warranty