

Date: 3/23/05

By: Bruce T. Travis Sr.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Marvin L. FLOSI D.D.S.

R.E. Number: 94954

Reason for inspection: Fire without pulling trigger

FIREARM

Manufacturer: Rem.

Model: 600

Serial Number: 6569776

Date of Manufacture: 4/73

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: Has been updated

Headspace: —

Function evaluation:

Feeding: —

Extraction/ejection: —

Trigger pull: 4#

Manual safety: OICWY-BOLT LOCK

Test firing results (if applicable): —

DISPOSITION

could not duplicate concern. Replace TP/A
Good - Will gesture to restore confidence in rifle.
AT N/C 230145

ADDITIONAL COMMENTS