

RECEIVING AND ESTIMATING REPORT

COMMENTS
ATTN K GREEN

INITIAL JJM	CUSTOMER ORDER NO.		DATE RECEIVED 10/30/90		DATE OPENED 10/31/90	DATE CODE PI 6-88	SERIAL NUMBER C6265415	MODEL AND GRADE 700 7MMAG BDL	ORDER R 90-2865
ACCESSORIES W/STUDS									

FROM:

BURNS, JOHNNY
3336 COUNTRY CLUB DR
CHARLOTTE NC 28205

SHIP TO:

~~BURNS, JOHNNY~~
~~3336 COUNTRY CLUB DR~~
~~CHARLOTTE~~ NC
28205

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

↓ J. P. FOSTER
5018 CAXILION DR.
CHARLOTTE, NC 28226

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☒ ^{LIVE} NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"GUN FIRED WHEN SAFETY WAS PUSHED OFF"

MAIN FAULT: Trigger assembly rusted from unknown source. Internal parts not moving properly.

Note: barrel rusty at pressure point location and, rear guard screw rusty. Appears rifle was wet at some time & not properly maintained.

PARTS: Per J. Foster (Sales Rep) instructions, rifle to be return shipped to him via U.P.S. NEXT DAY

Replace Trigger assembly at no charge as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS02499