

RECEIVING AND ESTIMATING REPORT						COMMENTS		ORDER R 92-13568		
INITIAL		CUSTOMER ORDER NO.								
DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER		NEW SERIAL NUMBER		
06/19/92		06/22/92		DJ 9-89		C6442980				
ACCESSORIES		SCOPE BASE				MODEL AND GRADE				
W/STUDS						700 7MM MAG AS				
FROM:						SHIP TO:				
GUNROD, DAVID 143 NORTH PENNOCK UPPER DARBY PA 19082						GUNROD, DAVID 143 NORTH PENNOCK UPPER DARBY PA 19082				
CUST NO: 062635 C.D.D.										
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE		CLEAN/TEST		ESTIMATED		
				1				7-7		
GUN CONDITION						PROM. DATE		VIA		
☐ NEW ☐ LIGHTLY WORK ☐ WORK ☐ VERY WORK ☐ UNREPAIRABLE ☐ BARRED								UPS		
						REPAIR CHARGE				
						EXCISE				
						TAX				
						INSURANCE				
						UPS				
						PARCEL POST				
						TOTAL				
CUSTOMER CONCERN		AMMO		FUNCTION		FINISH		ACCURACY		
CYCLE				B1						
TRIGGER GROUP				B2						
BOLT ASSY.				B3				E2		
BARREL ASSY.				B4				E3		
REC. ASSY.				B5				E4		
WOOD				C1		D3		E5		
METAL				C2						
MAIN FAULT: 1) Unable to duplicate complaint - trigger assembly operates properly every request. Trigger pull - 5 pounds. Rear lift - .012" 2) Front end of trigger assembly still in chamber 3) Stock is cracked through guard screw holes from front to back										
PARTS					COMMENTS					
					1) Remove stock cap from chamber					
					2) Have stock checked for abuse (Wear or not?)					
					3) Offer to replace trigger at \$200 unless all parts good - well, or we can return with present trigger assembly					
REPAIRMAN					PROOF		CLEAN		TEST	
BWT										
GALLERY TESTER					DATE		DATE		DATE	

OFFICE COPY

RD6925 REV. 1/9

PS02711