

Date: 11/2/04
By: Bruce Trainor

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Rich Grogg

R.E. Number: 87193

Reason for inspection: FSR

FIREARM

Manufacturer: Rem Model: 700

Serial Number: ML091154 Date of Manufacture: 3/03

Overall external condition: Good

Barrel condition: okay

Receiver condition: okay

Stock condition: okay

Bolt/firing pin condition: okay

Trigger assembly condition: _____

Engagement: _____

Adjustments/alterations: _____

Other: connector worn/chipped at rear contact

Headspace: _____

Function evaluation: _____

Feeding: _____

Extraction/ejection: _____

Trigger pull: _____

Manual safety: okay

Test firing results (if applicable): —

DISPOSITION

unnatural wear on connector surface. Replace
complete TPA checkered at N/C. Warranty

ADDITIONAL COMMENTS

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There are approximately 20 lines visible. The paper has some minor blemishes and dust specks, particularly near the top edge. The overall appearance is that of a clean, unused piece of stationery.