

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS WOG 1 OF 2 W/LEUPOLD 3X9 SCOPE & CAPS <i>in separate box</i> STOCK NOT OUR MFG	
DATE RECEIVED 11/22/91	DATE OPENED 01/29/91	DATE CODE RT 11-70	SERIAL NUMBER 6382936	MODEL AND GRADE 700 270	ORDER R 91-0299
ACCESSORIES W/STUDS <i>4/6.14</i>		SCOPE MNTS		SCOPE BASE	HARD CASE
FROM: HOPSON, DAVID L 11446 LOYOLA CYPRESS TX 77429			SHIP TO: HOPSON, DAVID L 11446 LOYOLA CYPRESS TX 77429		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED
				VIA	UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"My 270 has fired several times throughout the years by simply pulling the gun off safety"

Tripin has been improperly adjusted outside the factory as evidenced by non-Remington Sealant on the adjusting screws. (excessive over travel & insufficient retention spring force - tripin is not retracting consistently - tripin pull varies from 2 1/2 pounds to 4 1/2 pounds)
Seal-left O.K. at .011"

Do not present tripin assembly to gunsmith, if possible, if not, offer new tripin assembly at 1/2 normal cost as gesture of good-will.

REPAIRMAN <i>BEA</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/9

PS03096