

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00068644

Description/Serial Number

A6216600

Repairman - Richard Hilts

Date Received - 9/2/2003

Account # - R-

Model 700 Center Fire Caliber: 7 MM

Estimate Date - 8/20/2003

REM MAG

Current Date - 9/3/2003

Customer

GEORGE HART

9640 BAUER RD

P.O. BOX 371

BREWERTON, NY 13029 US

Return To

GEORGE HART

9640 BAUER RD

P.O. BOX 371

BREWERTON, NY 13029 US

Phone (H) (315)-676-2173 XHOM

Phone (W) (315)-473-5525 X705

Fax

Email

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M238 CLEAN & INSPECT
M991 CHANGE TO SYN STOCK BDL OR
DBM

Reported

M123 FORWARD TO PRODUCT SERVICE F
M238 CLEAN & INSPECT
M992 FIRES WHEN GOING FROM SAFE TO

Material # Material Desc

Part

F106170 700 SYN STK ASSB BDL L/A

F26345 700 TRIG ASSB RH

Part Total:

Service

4000104 ARMS SERV SHIPPING & HANDLING

4000116 GR-LABOR

4000118 GR-CLEAN

4000119 GR-TEST

Service Total:

Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
1	1	0	N
1	1	0	Y
2	2	0	
0	0	0	Y
20	20	0	N
1	1	0	Y
1	1	0	Y
22	22	0	

Problem/Notes

fires when going from safe to fire action & trigger dirty parts working sluggish clean action
QUOTE \$20.00 to replace trigger

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

PS03133