

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-12564INITIAL
FJBCUSTOMER ORDER NO.
008813

DATE RECEIVED

04/11/94

DATE OPENED

04/11/94

DATE CODE

XT 12-70

SERIAL NUMBER

3657724

NEW SERIAL NUMBER

MODEL AND GRADE

700 264 WIN MAG/SS

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

HANLON, JAMES
RR 1 RT 104
PO BOX 33
MANTVILLE

NY 13111

SHIP TO:

HANLON, JAMES
RR 1 RT 104
PO BOX 33
MANTVILLE

NY

13111

CUST NO: 095658 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

DOOR

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☒ MARRED

Product Service

REPAIR CHARGE 20

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	Fires when safety is released also when in the				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.						F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Mag. 12-70 Unable to duplicate customers concern as well. Found pull and trigger overtravel screws have been adjusted outside of the factory and the sear was gummed up in housing. We do not recommend that the trigger be adjusted outside the factory and metal parts should be lubricated periodically with a light coat of light oil. Replace trigger assy. at special price strictly as a gesture of good will.

PARTS

COMMENTS

Trigger pull measured 5 to 5 1/2 LBS as received. sear lift was .009

• Sear sticks in housing
• Bolt stop sticks

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

R06925 REV 1/94

PS03203