

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-12424INITIAL
FPS

CUSTOMER ORDER NO.

W/BTM. HALF OF SCOPE BASE

XCFS ✓

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/07/94

04/08/94

RI 11-28

A6383869

700

22-250

RDL

ACCESSORIES

W/STUDS

L/REAR SIGHT

FROM:

SHIP TO:

JACKSON, EUGENE M.
RT 1 BOX 118
MILLBORO
UPS

VA 24460

JACKSON, EUGENE M.
RT 1 BOX 118
MILLBORO
UPSVA
24460

CUST NO: 095584 CLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Product Service

COD

REPAIR CHARGE

20.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Upon receipt, we were unable to duplicate the customer concern. Examination of the trigger assembly and action revealed that the rifle is loaded with a heavy duty and gritty substance. Bolt stop, when working properly. Trigger pull - 5 lbs. Bolt made a good opening. 5 lb. lift - .007

#26345 Trigger assembly

Replace complete trigger assembly & clean action at 1/2 normal cost, as gesture of good will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

Remington
AM Servi.
Ilion, N.Y.
Gentlemen:
I am returning
rifle.
I purchased
as a use
unless he
has disc
would li
as I lik
Please in
again.

to A/S
5/18/94