

Date: 12/14/04

By: Bruce Travis Sr.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: HARRY F. Kite

R.E. Number: 89524

Reason for inspection: FSP

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: B6753290 Date of Manufacture: 10/85

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: Adjusted

Adjustments/alterations: Adjusted

Other: Rusty inside

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: _____

Manual safety: _____

Test firing results (if applicable): _____

DISPOSITION

TRIP. Froze up/rusted. Replace TPA AT 1/2 MSP. Quote

ADDITIONAL COMMENTS