

Bryce Knight

7419 Harris

Raytown, Mo. 64133



Safty Malfunctions
Ramington Arms
1007 Market Street
Welmington, Delaware 19898

om



RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-16371

ATTN: JACK KAST
STOCK NOT OF REM. MAN.

TIAL DC	CUSTOMER ORDER NO.				
TE RECEIVED 05/20/94	DATE OPENED 05/20/94	DATE CODE BZ 1/75	SERIAL NUMBER 6711465	NEW SERIAL NUMBER	MODEL AND GRADE 700 222REM.
CESSORIES	W/STUDS	SCOPE MNTS	SCOPE BASE		

DM:

KNIGHT, BRYCE
7419 HARRIS
RAYTOWN

MO 64133

SHIP TO:

KNIGHT, BRYCE
7419 HARRIS
RAYTOWN

MO
64133

CUST NO:097644 C.O.D.L

COUNT NUMBER 263103	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
N CONDITION NEW LIGHTLY WORN WORN VERY WORN UNREPAIRABLE MARRED					REPAIR CHARGE 20.00 EXCISE TAX INSURANCE UPS 5.00 PARCEL POST TOTAL 28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE		B1				
IGGER GROUP		B2			E1	F1
ILT ASSY.		B3			E2	F2
RREL ASSY.		B4		D1	E3	F3
C. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
TAL			C2			

Manufacturer 1-75 firing pin follows down when bolt is closed properly. All trigger adjusting screws have been checked outside of Factory. We do not recommend that the trigger be adjusted outside of the Factory. Exchange trigger assy. at a special price strictly as a gesture of good will.

ITS	COMMENTS <i>Trigger pull measured 2 to 2 1/4 lbs as recd. near lift was .003</i> <i>Stock not of Remington Mfg.</i>					
REPAIRMAN		PROOF	CLEAN ☒	TEST ☒	TARGET	PATTERN
GALLERY TESTER		DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD8925 REV. 1/94

PS03666