

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number

RE00049887

Account # - R-

Description/Serial Number

6462935

Model 700 Center Fire Caliber: 243 ADL

Date Received - 8/1/2002

Estimate Date -

Current Date - 8/9/2002

Customer

JACK LANDON JR

120 PARADISE PARK RD

SHERIDAN, WY 82801 US

Return To

JACK LANDON JR

120 PARADISE PARK RD

SHERIDAN, WY 82801 US

Phone (H) (307)-672-8431

Phone (W)

Fax

Email jlandon@fiberpipe.net

Problems			
Reported		Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE FO
		M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	Action and trigger assembly covered with dirt and a heavy sticky substance - Poorly maintained. Replace trigger assembly \$20.00. D.S.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
Service	Total:	22	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

JACK LONDON JR
120 PARADISE PARK RD
SHERIDAN WY 82801




WY 828 0-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1192 2300



BILLING: P/P

INV#: RE00049887

ASC 05.00 J69X/J64X 16.0A 01/2002

PS03770